



# Underground Storage Tank Facility Inspection Report

## Facility Information

Facility Id:	2036972	Inspection Date:	9/13/2017
Registered Name:	Muffys Market	Inspected by:	Lorrie Smith
Registered Address:	2024 Crest Ridge Rd Martinsville VA, 24112	Actual Address:	2024 Crest Ridge Rd Martinsville VA, 24112

### Tank Owner

Carter Bank & Trust  
1300 Kings Mountain Rd  
Martinsville VA, 24112  
(276) 656-1776

### Tank Owner Contact

Andrew Meece  
1300 Kings Mountain Rd  
Martinsville VA, 24112  
(276) 656-1776  
andrew.meece@bsvacorp.com

## Compliance Summary

### Spill Prevention

This inspection did not identify any Spill Prevention compliance issues which need to be addressed at this time.

### Overfill Protection

This inspection did not identify any Overfill Protection compliance issues which need to be addressed at this time.

### Pipe Release Detection

This inspection did not identify any Pipe Release Detection compliance issues which need to be addressed at this time.

### Tank Release Detection

This inspection did not identify any Tank Release Detection compliance issues which need to be addressed at this time.

**Pipe Corrosion Protection**

This inspection did not identify any Pipe Corrosion Protection compliance issues which need to be addressed at this time.

**Tank Corrosion Protection**

This inspection did not identify any Tank Corrosion Protection compliance issues which need to be addressed at this time.

**Secondary Containment**

This inspection did not identify any Secondary Containment compliance issues which need to be addressed at this time.

**Temporary Closure**

This inspection did not identify any Temporary Closure compliance issues which need to be addressed at this time.

**Operator Training**

This inspection did not identify any Operator Training compliance issues which need to be addressed at this time.

**Registration**

This inspection did not identify any Registration compliance issues which need to be addressed at this time.

**Inspection Comments**

**Tank Information**

Tank Num	Contents	Capacity	Status	Date Installed	Spill Prevention	Overfill Device
4	GASOLINE	2000 gal	TEMP OUT OF USE	4/7/1999	No	ALARM
5	GASOLINE	2000 gal	TEMP OUT OF USE	4/7/1999	No	ALARM

Material of Construction		
Tank Num	Tank Materials	Piping Materials
4	Composite (Steel Clad w/ Fiberglass/ACT-100/ACT-100U)	Fiberglass Reinforced Plastic
5	Composite (Steel Clad w/ Fiberglass/ACT-100/ACT-100U)	Fiberglass Reinforced Plastic

Release Detection					
Tank Num	Tank RD Method	Piping	Piping RD Method	Last LTT	Last ALLD Test
4	Statistical Inventory Reconciliation	NO VALVE: SUCTION		N/A	N/A
5		NO VALVE: SUCTION		N/A	N/A

Corrosion Protection System		
Tank Num	Last Tank CP Test	Last Pipe CP Test
4		
5		

## Site Sketch