OSE/F	Page 1 of 7 PE Report For:
Construction	Voluntary Upgrade Certification Subdivision Permit Letter Approval
Property Location:	
911 Address: TBD Slings Gap Rd	State /City: Bent Mountain, VA
Lot Section	Subdivision
GPIN or Tax Map # 21-9	Health Dept ID # Franklin County
Latitude	Longitude
Applicant or Client Mailing Address:	
Name: Loud Water, LLC	Phone: 540-761-9166 Email: sam@woltz.com
Street: 23 Franklin Rd.	
City: Roanoke	State VA Zip Code 24011
Prepared by:	
OSE Name Stephen D. Dalton	License # 1940001068
Address 305 Oak Street	
City Hillsville	State _VA Zip Code 24343
PE Name	License #
PE Name	License #
Address	
Address	State Zip Code
Address	State Zip Code Date of Revision #1
Address City Date of Report 5/27/24 OSE/PE Job #	State Zip Code Date of Revision #1 Date of Revision #2
Address City Date of Report 5/27/24 OSE/PE Job # Contents/Index of this report (e.g., Site Evaluation Summa OSE Report	State Zip Code Date of Revision #1
Address	Date of Revision #1 Date of Revision #2 ry, Soil Profile Descriptions, Site Sketch, Abbreviated Design, etc.) ✓ System Specs Abbreviated Design ✓ Construction Drawing ✓ Site Sketch
Address City Date of Report 5/27/24 OSE/PE Job # Contents/Index of this report (e.g., Site Evaluation Summa OSE Report	Date of Revision #1 Date of Revision #2 ry, Soil Profile Descriptions, Site Sketch, Abbreviated Design, etc.) ✓ System Specs ✓ Construction Drawing ✓ Well Specs ✓ Map
Address	Date of Revision #1 Date of Revision #2 ry, Soil Profile Descriptions, Site Sketch, Abbreviated Design, etc.) ✓ System Specs Abbreviated Design ✓ Construction Drawing ✓ Site Sketch
City	Date of Revision #1 Date of Revision #2 ry, Soil Profile Descriptions, Site Sketch, Abbreviated Design, etc.) ✓ System Specs ✓ Construction Drawing ✓ Site Sketch ✓ Well Specs ✓ Pump Specs Reserve rerein were conducted in accordance with the applicable provisions of the Private Well Regulations (12 VAC5-630), the Regulations for applicable laws, regulations and policies implemented by the Virginia ny professional license required by the laws and regulations of the ency charged with licensure to perform the work contained herein. The practice of engineering was a fire the contained by the laws and regulations.

5/27/24

Commo	nwealth of V <u>ir</u> gini	a	VDH Use only
Application for	or:☑Sewage System☑Water	Supply	VDH Use only Health Department ID# Due Date
Owner Loud V	/ater, LLC		Phone 540-761-9166
Mailing Address	23 Franklin Rd.		Phone
	Roanoke VA	24011	
Agent	Southwest Soils, Inc.		Fax
Mailing Address	305 Oak St.		
	Hillsville VA 24343		Phone
Site Address TBI	Slings Gap Rd		Fax
Be	nt Mountain, VA		_{Email} sam@woltz.com
Directions to Prop	erty: Entrance is NW of 10809 S	lings Gap Rd	Email Sameworks.com
Subdivision		Section	Block Lot
Гах Мар 21-9	Other Property Identi	fication	Dimension/Acreage of Property 28.277 acres
Proposed Use: Single Family Other (describe) Basement Yes Conditional permit Reduced wate	r flow Limited Occupancy Inte	Multi-Family Dwe No Fixtu If yes, which conditions rmittent or seasonal use tter? Yes No *There	res in Basement Yes O NoO
		ater Supply	
	ply be Public or O Private?	Is the water supply	© Existing or ©Proposed?
f proposed, is this	a replacement well? OYes ONo	If yes, will the old	I well be abandoned? OYes ONo Will
	in 50' of the proposed well be termite		
Well Type (e.g. do	omestic use, agricultural, irrigation, etc	.) Domestic	
s this property in	All leed to serve as your (owners) principa	Applicants	Voc
approved. Is a Per	ust be accompanied by private sector ention for Service form attached?	evaluations and designs,	unless a petition for VDH services is
oposed buildings an illding location and give permission to the occessing this application.	the proposed well and sewage sites must be e Virginia Department of Health to enter o tition and to perform quality assurance check the control of the contr	ewage system. When the se clearly marked and the property described where of evaluations and desired	of the property and a site sketch. For water in should show your property lines, actual and/or ite evaluation is conducted the property lines, operty sufficiently visible to see the topography during normal business hours for the purpose of ins certified by a private sector Onsite Soil water water supply has been constructed and
	tyto O. D. e.	5	/27/24
ignature of Owne	r/ Agent		Date Date
is form contains p	ersonal information subject to disclosure	under the Freedom of In	formation Act. Revised 7/1/2019
			The state of the s
			ONSITE SON

Site and Soil Evaluation Report

	VDH Use Only
HDIN:	J

Soil Information Summary 1. Position in landscape satisfactory: Yes No Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. Not observed 4. Free Water Present: Yes No Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: 40 min/in at 40 inches Texture Group: I II III III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersel septic Tank Effluent (proposed level of treatment at time of evaluation) to be placed at 40 (inches)	epartment
Property Address: TBD Slings Gap Rd Tax Map/GPIN #: 21-9 Subdivision: Section: Section: Block: L Soil Information Summary 1. Position in landscape satisfactory: Yes No Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. Not observed 4. Free Water Present: Yes No Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: Texture Group: I III III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: Signature: Stie approved: Absorption Trenches (describe dispersal area, e.g., absorption trenches) dispersal	.ot:
Soil Information Summary 1. Position in landscape satisfactory: Yes No Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. Not observed 4. Free Water Present: Yes No Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: 40 min/in at 40 inches Texture Group: I I II III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: Georgia Absorption Trenches (describe dispersal area, e.g. absorption trenches) dispersed to the placed at 40 (inches).	.ot:
Soil Information Summary 1. Position in landscape satisfactory: Yes \ No \ Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. \ Not observed 4. Free Water Present: Yes \ No \ Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches \ Not observed 6. Soil percolation rate estimated: Yes \ No \ Estimated rate: 40 min/in at 40 inches of the results of the results of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersel captures are grayed at 40 (inches).	Lot:
1. Position in landscape satisfactory: Yes No Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. Not observed 4. Free Water Present: Yes No Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: 40 min/in at 40 inches Texture Group: I III III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersed to the placed at 40 (inches).	
1. Position in landscape satisfactory: Yes No Describe landscape position: Sideslope 2. Slope: 32 % 3. Depth to rock/impervious strata: Max. 70 in. Min. 60 in. Not observed 4. Free Water Present: Yes No Range in inches: 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: 40 min/in at 40 inches Texture Group: I III III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersed to the placed at 40 (inches).	
2. Slope: 32	
 4. Free Water Present: ☐ Yes ☐ No Range in inches: ☐ 5. Depth to seasonal water table (gray mottling or gray color): ☐ inches ☐ Not observed 6. Soil percolation rate estimated: ☐ Yes ☐ No Estimated rate: ☐ Min/in at ☐ III ☐ IV 7. Percolation test performed: ☐ Yes ☐ No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: ☐ Site approved: Absorption Trenches ☐ (describe dispersal area, e.g. absorption trenches) disperseptic Tank Effluent (proposed level of treatment at time of evaluation) to be placed at 40 (inches) 	
 4. Free Water Present: ☐ Yes ☐ No Range in inches: ☐ 5. Depth to seasonal water table (gray mottling or gray color): ☐ inches ☐ Not observed 6. Soil percolation rate estimated: ☐ Yes ☐ No Estimated rate: ☐ Min/in at ☐ III ☐ IV 7. Percolation test performed: ☐ Yes ☐ No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: ☐ Site approved: Absorption Trenches ☐ (describe dispersal area, e.g. absorption trenches) disperseptic Tank Effluent (proposed level of treatment at time of evaluation) to be placed at 40 (inches) 	
 5. Depth to seasonal water table (gray mottling or gray color): inches Not observed 6. Soil percolation rate estimated: Yes No Estimated rate: 40 min/in at 40 inches inches Texture Group: I II III III IV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersal	
 6. Soil percolation rate estimated: ■ Yes □ No Estimated rate: 40 min/in at 40 inches of Texture Group: □ I ■ II □ III □ IV 7. Percolation test performed: □ Yes ■ No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature:	
Texture Group: I II III IIV 7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersoration trenches (proposed level of treatment at time of evaluation) to be placed at 40 (inches)	d 41.
7. Percolation test performed: Yes No If yes, provide additional data on percolation test results Name and title of evaluator: Stephen Dalton OSE Signature: (describe dispersal area, e.g. absorption trenches) dispersal trank Effluent (proposed level of treatment at time of evaluation) to be placed at 40 (inches)	aeptn
Name and title of evaluator: Stephen Dalton OSE Signature:	
Signature: Site approved: Absorption Trenches (describe dispersal area, e.g. absorption trenches) dispersal Tank Effluent (proposed level of treatment at time of evaluation) to be placed at 40 (inches)	١.
(proposed level of treatment at time of evaluation) to be placed at 40	
(proposed level of treatment at time of evaluation) to be placed at 40	rsing
site designated on posmit Site and 1 and 270	denth at
site designated on permit. Site provides a total of 120 square feet of absorption area for prin	nary and
reserve (if applicable).	nary and
Site disapproved: Reasons for rejection (check all that apply)	
 Position in landscape subject to flooding or periodic saturation. Insufficient depth of suitable soil over hard rock. Insufficient depth of suitable soil to seasonal water table. Rates of absorption too slow. Insufficient area of acceptable soil for required absorption area, and/or reserve area. Proposed system too close to well. Other (specify) 	·

OSTEPHEN D. DALTON Lic. No. 1940001068


Date o	of Evaluati	ion: 5/22/24	Profile Description	
_	04	•	SOIL EVALUATION REPORT	
Proper	rty ID: 21	-9		
private (all struc the reve	Onsite Soil I tural feature rse side of the	Evaluator or es (i.e. sewag	ent conducts the soil evaluation the location of profile holes may be shown on the mit or the sketch submitted with the application. If soil evaluations are conducted Professional Engineer, location of profile holes and sketch of the area investigated ge disposal systems, wells, etc.) within 200 feet of the site and reserve site shall be prepared on a separate page and attached to this form.	by a
	application s		See Construction Permit	s form
Hole #	Horizon	Depth (Inches)	Description of color, texture, etc.	Texture
1	Α	0-10	Dark Vollowich Proves (40VD 0/0) LOAM	Group
	Bt	10-26	Dark Yellowish Brown (10YR 3/6) LOAM Brown (7.5YR 5/4) SANDY CLAY LOAM	IIb
	С	26-72		llb
			Dark Yellowish Brown (10YR 4/6) SANDY LOAM, more dense at 50"	lla
2	А	0-8	Dark Yellowish Brown (10YR 3/6) LOAM	III
	Bt	8-28	Strong Brown (7.5 YR 5/6) SANDY CLAY LOAM	IIb
	С	28-60	Yellowish Brown (10 YR 5/6) SANDY LOAM	llb
			(100) 0.11.01 207 101	lia
				-
3	Α	0-10	Dark Yellowish Brown (10YR 3/6) LOAM	IIb
	Bt	10-30	Dark Yellowish Brown (10YR 4/6) SANDY CLAY LOAM	ilb
	С	30-60	Brown (7.5YR 5/4) LOAM	IIb
-				
				data.
REMAR	KS.		CALT	HOADE
CLIVIAN			A PHY	Ville W
			AK SAC	
				Z
			OSTEPHEN-E Lic, No. 19	-DALTON - 40001068 5
			THE CONST	TE SOIL E

System Specifications

	VDH Use Only
HDIN: _	•

Application Information	
Name: Loud Water, LLC	Address: 23 Franklin Rd.
Phone: <u>540-761-9166</u>	Roanoke VA 24011
Location Information	
Tax Map/GPIN #: 21-9	Property Address: TBD Slings Gap Rd Bent Mountain, VA
Subdivision: Section:	Block: Lot:
Directions: NW of 10809 Slings Gap Rd	
General Information	
Property Type (e.g. residential): Residential	Number of Bedrooms: 3
Daily Flow: 450 gpd	Conditions:
Notes:	
Sewer Line	
Diameter: 4 in. Material: SCH 40 PVC	(or equivalent) Notes: deanouts every 50'
Pretreatment Unit(s)	
Treatment Level:	Septic Tank Capacity: 1,000 gallons
Number of Septic Tanks 1	Size of Septic Tank(s) 1,000 gallons
Per the Sewage Handling and Disposal Regulations, cl	neck which option(s) chosen:
■ Septic tank with inspection port □ Septic tank with	effluent filter Reduced maintenance continued
Secondary treatment device(s), if applicable:	The interest in Reduced maintenance septic tank
Notes: PVC 40 4" Tees	
Conveyance Line	Distribution Method and Header Lines
Conveyance Method: Gravity	Distribution Method: 4" SCH 40 PVC
If pumping, include pump specifications sheet.	No. of boxes: 1 No. of outlets: 8+
Material: SCH 40 PVC Diameter: 4"	Surge or splitter box required: ☐ Yes ■ No
Notes: 6" fall per 100'	Header Line Material: SCH 40 PVC
Percolation Lines/Absorption Area	
Dispersal Method (e.g. laterals, pad, mound): laterals	
If using pressure dispersal (e.g. drip), include pressure	dispersal specifications sheet.
No. of laterals/pads: 4 Length of lateral(s)/pad	(s): 60 ft. Width of lateral(s)/pad(s): 36 in.
Center to center spacing: 12 ft. Installation de	pth: 40 in. Aggregate depth: N/A in.
Size/Type of Aggregate: Infiltrator Chambers	Lateral/pad slope: 2"-4" in. per 100 ft
Reserve Area Provided: % Notes:	FALTH OF
DH a comp ThY - 4	ST OH YE
Please Note:	

Lic. No. 1940001068



Well Specifications

HDIN:	VDH Use Only	

Applicant Information				
Name: Loud Water, LLC		Address: 23 Fra	ınklin Rd	
Phone: 540-761-9166		Roanoke	VA	24011
Location Information				
Tax Map/GPIN #: 21-9		Property Address	ss: TBD Slings Gap	Rd Bent Mountain
Subdivision:		ction:	Block:	Lot:
Directions: NW of 10809 Slings Gap	Rd			
General Information				
Well Purpose (select all that apply): Dome	estic Dr	nking Water	☐ Agricultu	ıral
☐ Irrigation ☐ Indus	strial/Co	mmercial	☐ Geothern	
Well Class: III-C		Minimum Casin		
Estimated Water Usage: 450			t Depth: 20	
Horizontal Setbacks				
Distance from Building Sewer: 50	ft.	Distance from F	Pretreatment Unit(s	s): ft.
Distance from Conveyance System: 50			bsorption Area:	
Distance from Property Line:	ft.		oundations:	
Distance from other source(s) of contamination	on: 10	0 _{ft.}		
List other source(s):				
Note:				
50'+ off property lines bordering agricultural	propert	y 50'+ off found	ations if building is	s termite treated
				- Ionnio Roaled



